

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar  
2 Name of Block/Road :- Katar / Lost - Katar To Khambar (VR 5)

### (A) For Road:

1. Damage Location/Chainage :- 1.215 Km, 1.30 Km, 1.40 Km, 3.25 Km, 5.55 Km
2. Damage Length :- 0.2181 Km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Brice bars
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.2181 Km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

E. B.

Rtd Muzaffar (Ct-1)

### GENERAL ABSTRACT

Name of Road L056-Katra T07 to Khanpur (VR5)

District Muzaffarpur


Block Katra

Division Muzaffarpur East-2


Length of Road (in Km) 6.210 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	12.396
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	12.396
TOTAL COST OF PROJECT IN LACS =		12.396

say 12.396 lac

  
11/1/21

JE  
RWD


  
11.1.2021

AE  
RWD

  
11/1

EE  
RWD

Technically approved for Rs 12.396 lac  
(Twelve lac thirty nine thousand six hundred only)

  
13.1.21  
SE

RWD work create  
muzaffarpur