Inspection Report for Flood Damage Work

Date:

- 1. Name of PIUs Gyan vibhallow
- 2. Name of Block/Road minabus/ pakhmaha to purama tak.

A. For Road

- 1. Damage Location/Chainage
- : 0.02010- 0.1000-, 0.200 kn, 0.34010, 0.60010, 0.70010n
- 2. Damage Length
- : 0.35451cm
- 3. Nature of Damage
- 4. Details of Restoration Works
- - Material being used in Restoration works: Brill but flowed sand
 - ii. Equipments/Tools being used in Restoration works:
 - ili. Procedure taken up in Restoration works:
 - iv. Restored Length

- B. For Bridge
- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works
 - i. Material being used in Restoration works:
 - Equipments/Tools being used in Restoration works: ii.
 - iii. Procedure taken up in Restoration works:
 - iv. Restored Length

Signature of JE/AE/EE

(Name of Inspector)

.E.G RMD work pronjen

muzerfaypur East-1