

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan Prabhakar

2. Name of Block/Road - Raila Ladi prasti Pond to Basmatra Ramsagar
Thakur Lane (Gaighat)

A. For Road ✓

1. Damage Location/Chainage : 0.350^{km}, 0.450^{km}, 0.850^{km}, 0.900^{km}, 1.10^{km}
(Length = 1.650^{km})

2. Damage Length : 0.1539^{km}

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick bats .

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length : 0.1539^{km}

× B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

i. Material being used in Restoration works :

ii. Equipments/Tools being used in Restoration works:

iii. Procedure taken up in Restoration works :

iv. Restored Length :

Signature of JE/AE/EE

Signature

(Name of Inspector)

EE
RWD works Division
myzstfor pur Ealt-1

GENERAL ABSTRACT

Name of Road	Raila Ladi PMGSY Road to Brahmoha Ramsagar Thakur		
District	Muzaffarpur		
Block	Gaighat		
Division	Muzaffarpur East-2		
Length of Road (in Km)	1.650 Km		

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Earthwork	0.000
1	Jhama metal	2.189
2	Sand Filling	A 6.070
3	Sand Bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	A 2.260
TOTAL COST OF PROJECT IN LACS =		A 2.260

Recd. 2.19 L

Scanned with CamScanner

AE
RWD

EE
RWD

Technically Approved for Ps. 2.19 Lac
(Rupees two Lac, nineteen thousand only.)

11/24
SE 4-1-24
pud work circle
myzifur pur