

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar

2. Name of Block/Road - minapur/ Belahi' Luchi' Road but talai to Hryatal deni
mandal via Kusmi' talai.

A. For Road

1. Damage Location/Chainage : 0.100km, 0.150km, 0.200km, 0.500km, 0.600km, 0.700km, 0.900km

2. Damage Length : 0.132km

3. Nature of Damage :

4. Details of Restoration Works :

- Material being used in Restoration works : Brick ball & local sand
- Equipments/Tools being used in Restoration works:
- Procedure taken up in Restoration works :
- Restored Length : 0.132km

B. For Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :

- Material being used in Restoration works :
- Equipments/Tools being used in Restoration works:
- Procedure taken up in Restoration works :
- Restored Length :

Signature of JE/AE/EE

[Signature]
18.11.20
Signature

(Name of Inspector)

EE

RWD works Division

Muzaffarpur East - I