

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- CRPF camp mohammadpur to malpur via. Simrasta

(A) For Road: ✓ Basudeo Path

1. Damage Location/Chainage :- 0.550km, 0.625km, 0.940km, 1.210km, 1.50km, 3.2km, 3.8km, 3.95km, 4.40km
2. Damage Length :- 0.542km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick bats
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.542km

(Length = 5.5km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

EE  
RWD WORK DIVISION  
muzzaffarpur East-1

### GENERAL ABSTRACT

Name of Road CRPF camp mohammadpur to Mahpur via Simarwara Basudeo path

District Muzaffarpur

Block Bochaha

Division Muzaffarpur East-2

Length of Road (in Km) 5.150 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	31.139
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.143
	GRAND SUB TOTAL	31.281
TOTAL COST OF PROJECT IN LACS =		31.281

3475 31.28 Lac

*[Signature]*  
31/12/2020

JE  
RWD

*[Signature]*  
31/12/20

AE  
RWD

*[Signature]*  
31/12

EE  
RWD

Technically Approved for Rs 31.28 Lac  
(Rupees thirty one Lac, twenty eight thousand only.)

*[Signature]*  
16.1.21  
SE  
RWD work circle  
muzaffarpur