## Inspection Report for Flood Damage Work

## Date:-1 Name of PIUs: - Gyan vibbaker 2 Name of Block/Road: - Raghopus to Dymanna (Galghat) (A) For Road: 1. Damage Location/Chainage :- 0.450, 1.70km, 1.8km, 4.50km, 5.50km (Leytu: 7.5km) 2. Damage Length :- 492.7 m 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:- Brick bats (i) Equipment's/Tools being used in Restoration works:-(ii) Procedure taken up in Restoration works: (iii) :- 0, 492 km Restored Length (iv) × (B) For Bridge: 1. Damage Location/Chainage 2. Damage Length 3. Nature of Damage 4. Details of Restoration Works :-(i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

Signature

PWD WORK DIVISION
MUZYTHEY PUR ECULT

## **GENERAL ABSTRACT**

Name of Road

Raghopur to Dumraon

District

Muzaffarpur

Block

Gaighat

Division

Muzaffarpur East-2

Length of Road (in Km)

7.500 Km

SI. No. DESCRIPTION		
4	Jhama metal	AMOUNT (LAKHS)
1	Jilailia illetai	9.505
2	Sand Filling	0.000
3 Sand bag	Sand had	0.000
	Salid bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	9.505
TOTAL C	OST OF PROJECT IN LACS =	
TOTAL COST OF FROMEOT IN LACS =		9.505

Says 9. 51 Lic.

JE JE

RWD

X-113120

ΑE

RWD

EE A

Technically Approved for B 9.51 lac (pupees nine lac fifty one thousand only).

EMD MORK CIRCLE