## **Inspection Report for Flood Damage Work**

## Date:-1 Name of PIUs :- Gyan Vibbakar 2 Name of Block/Road: - makbur vishwanath Rajak house to Bashauli siman 1. Damage Location/Chainage :- 0.3 40km, 0.430km, 0.520km, 0.520km, 0.710km, 2. Damage Lenoth (A) For Road: :- 383.2m (0.3832 km) 3. Nature of Damage 4. Details of Restoration Works: Material being used in Restoration works:- brick bats. (i) (ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works: :- (0.3832 km) (iv) Restored Length (B) For Bridge: X 1. Damage Location/Chainage :-2. Damage Length 3. Nature of Damage 4. Details of Restoration Works: (i) Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection)

EE RWD WORK DIVISION

myzattas þas East-1

## **GENERAL ABSTRACT**

Name of Road

Mahapur Vishwanath Rajak House to Bashauli Siman Anup Ray House

District

Muzaffarpur

Block

Bochaha

Division

Muzaffarpur East-2

Length of Road (in Km)

0.835 Km

		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	18.277
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	18.277
	GRAND SUB TOTAL	18.277
TOTAL	COST OF PROJECT IN LACS =	

5 mg 18.20 Lac

2011212

JE RWD Xxhall

^\_

Opt MIN

RWD

Technically Approved for B 18.28 24 C

Purees eighteen lac twenty eight thousand only.)

SE RND work tiscle

Scanned with CamScanner