

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- cond. of road from hoddan patti to seniya Gao ke nze
kumhrawil Siwan dist. (Galgahat)

(A) For Road: ✓

1. Damage Location/Chainage :- 0.450 km, 0.930 km, 1.50 km, 1.90 km, 3.50 km, 4.2 km
2. Damage Length :- 145.3 m (0.1453 km) (Length = 5.570 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.145 km

X (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division

myzatterpur East-1

GENERAL ABSTRACT

Name of Road Construction of Road From Goddan Patti to Seviya Gao Ke Age Kumhrauli Siwan Tak
District Muzaffarpur
Block Gaighat
Division Muzaffarpur East-2
Length of Road (in Km) 5.570 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	4.530
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	4.530
TOTAL COST OF PROJECT IN LACS =		4.530

Says 4.53 lac

[Signature]
JE
RWD

[Signature]
AE
RWD

[Signature]
EE
RWD

Technically Approved for Rs 4.53 lac
(Rupees four lac, fifty three thousand only).

[Signature]
SE
RWD work circle
muzaffarpur