

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Babbar

2 Name of Block/Road :- Badgama to Ladaur (haighat)

(A) For Road:

1. Damage Location/Chainage :- 1.00km, 1.50km, 1.80km, 1.95km)
2. Damage Length :- 97.06m (0.09706km) (Length = 4.75km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.097 km (0.09706km)

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD work Division
muzaffargarh East-1

GENERAL ABSTRACT

Name of Road Bhatgawan to Ladaura Path

District Muzaffarpur

Block Gaighat


Division Muzaffarpur East-2


Length of Road (in Km) 4.750 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.577
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	3.577
TOTAL COST OF PROJECT IN LACS =		3.577


SAY 3.58 Lac.


JE
RWD


AE
RWD


EE
RWD

Technically Approved for Rs. 3.58 Lac.
(Rupees three Lac, fifty eight thousand, only).


SE
RWD work circle
muzaffarpur