## FIELD INSPECTION REPORT

Date of Inspection :	1201/2021		District: NAWADA	
Division: RAJAULI		Length (km): 0.550	0.550	
Name of the Road:	1028 70	BH'A LUAHY		
Scheme/Programm		1 GTSNY		
Package No.:	NA	Road Id No.: 1050270	1827	
Status of the Project: Ongoing/Completed/Under Maintena			The state of the s	
Work is a case of:		Up gradation/ Maintenance		
SII No.	Parameters t	o be checked	Remarks	
1. Pavemen			1	
a) Road June	Road Junction condition			
b) Condition	Condition of Surfacing			
c) Riding Qu	Riding Quality			
d) Road Can	Road Camber			
e) Whether aggregate	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f) Contracti	Contraction Joints provided or not (CC Pavement)			
g) Compact	Compaction of flank/slope & raincuts if any			
Z Gross D	ainage	The state of the s	E Brokenie	
a) Condition	Condition of head walls in Hume pipe culverts including its painting S/SR			
	Condition of Abutment & Wing walls, Slab in RCC culverts			
c) Condition	Condition of railings/slab/approach for Bridges			
3 Road Fu	ralture			
stones/Pa	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
Comput	ice History		11.	
a) Status of	ATR's & any others		NA	

Overall Rating

,	
Satisfactory (S)	101
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: BINOD KUMAR

DESIGNATION: J.E., RWD. AKban perm

Scanned with CamScanner

INA