

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Harpur masry Road to satha harpur

(A) For Road: ✓

1. Damage Location/Chainage :- 0.005km , 0.035km
2. Damage Length :- 0.0357 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.0357 km

(Length = 1.5 km)

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road Harpur MMGSY Road to Satha Harpur

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km)

1.500 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	31.504
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	31.504
TOTAL COST OF PROJECT IN LACS =		31.504

Say 31.50 Lac

ah
31/12/2020
JE
RWD

K-14
31/12/20
AE
RWD

904
31/12
EE
RWD

Technically approved for Rs 31.50 Lac.
(Pures thirty one Lac fifty thousand only.)

hjm
1.6.1.7
SE
RWD works circle
muzaffarpur