

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- const. of madhuxpatti -to mahuaa mandir Jina wali

(A) For Road: ✓ sadak ka Nidhan

1. Damage Location/Chainage :- 0.200km, 0.350km, 0.410km, 0.520km, 0.80km, 1.20km
2. Damage Length :- 0.34476 km 1.60km, 1.90km, 2.20km
3. Nature of Damage :- 2.50km
4. Details of Restoration Works :- (Length = 2.98km)
(i) Material being used in Restoration works:- brick bats.
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:
(iv) Restored Length :- 0.34476 km

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
(i) Material being used in Restoration works:-
(ii) Equipment's/Tools being used in Restoration works:-
(iii) Procedure taken up in Restoration works:-
(iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division
muzaffarpur East-I

GENERAL ABSTRACT

Name of Road Construction of Madhurpatti to Mahurara Mandir jane wali Sadak ka Nirman
 District Muzaffarpur
 Block Gaighat
 Division Muzaffarpur East-2
 Length of Road (in Km) 2.980 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	10.569
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	0.000
	GRAND SUB TOTAL	10.569
TOTAL COST OF PROJECT IN LACS =		10.569

say 10.57 lac

GR
31/12/200
JE
RWD

10/12
31/12/20
AE
RWD

27/11
EE
RWD

Technically approved for Rs 10.57 Lsc)
 (Rupees ten lac fifty seven thousand only)

12/12/20
16.1.21
SC
RWS work circle
muzaffarpur