

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Lb83 Prayagwari to Beera (VRS3)

(A) For Road: ✓

1. Damage Location/Chainage :- 6.50km, 6.70km, 6.95km, 7.10km, 7.35km, 7.60km, 5.50km.
2. Damage Length :- 0.334 km (Length = 7.79 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats.
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.334 km

(B) For Bridge: X

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWD work Division
myzafferspur (East - I)

GENERAL ABSTRACT

Name of Road L083-Prayagbari to Barua(VR57)

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (in Km)

7.724 Km
4.000 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	17.141
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	17.141
TOTAL COST OF PROJECT IN LACS =		17.141

SAY 17.14 LAC

[Signature]
31/12/2020
JE
RWD

[Signature]
31/12/20
AE
RWD

[Signature]
21/12
EE
RWD

Technically Approved for Rs 17.14 LAC
(Rupees seventeen lac fourteen thousand only.)

[Signature]
16.1.21
SE
RWD WORK circle
muzaffarpur