

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Loss to house of Haradkishore Singh 48f chabhi

(A) For Road: ✓

1. Damage Location/Chainage :- 0.025km, 0.150km, 0.180km, 0.210km, 0.250km
2. Damage Length :- 122.0m (0.122km) (Length = 0.122km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.122km

(B) For Bridge: X

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE
RWD work Division
muzaffarpur East-1

GENERAL ABSTRACT

Name of Road L058 to House of Nandkishore Singh Urf Chabhi

District Muzaffarpur

Block Gaighat

Division Muzaffarpur East-2

Length of Road (In Km)

0.400 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		4.189
1	Jhama metal	0.000
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	4.189
	GRAND SUB TOTAL	4.189
TOTAL COST OF PROJECT IN LACS =		

4.19 LAC

Cal
20/11/20

JE
RWD

14/11/20
20/11/20

AE
RWD

Cal
20/11/20

EE
RWD

Technically Approved for Rs 4.19 LAC
(Rupees four LAC . nineteen thousand only.)

14/11/20
16.1.21
SE
RWD work circle
muzaffarpur