

## Inspection Report for Flood Damage Work

Date.: ..... 24.12.2020.

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Paroo
3. Name of Road/Bridge – Improvement of Repura Chowk To Boari Via Mahmaddpur Baran Road

### A. for Road


1. Damage Location/Chainage : 10 place (From 0.00 KM to 1.95 KM)
2. Damage Length : 77.46 M
3. Nature of Damage : Break at Road Cross with Embankment.
4. Details of Restoration Works :
  - i. Material being used in Restoration works : Bricks Ball, Local Sand.
  - ii. Equipments/Tools being used in Restoration Works : - Tractors, J.C.B, Rollers
  - iii. Procedure taken up in Restoration works : First - Bridge Ball filling in break portion. Then - Topping by Local Sand.
  - iv. Restored Length : \_\_\_\_\_ 77.46 M.


### B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
  - i. Material being used in Restoration works :
  - ii. Equipments/Tools being used in Restoration Works :
  - iii. Procedure taken up in Restoration works :
  - iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)