

Inspection Report for Flood Damage Work

Date.: 26/12/2020

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Sahebganj

3. Name of Road/Bridge – Meorhar Paharpur To Rup Chapra

A. for Road

1. Damage Location/Chainage : 000 300 M

2. Damage Length : 22 M

3. Nature of Damage : Road crest 8 ft/w sub-grade shoulder

4. Details of Restoration Works :

i. Material being used in Restoration works : —

ii. Equipments/Tools being used in Restoration Works : Tractor, JCB etc

iii. Procedure taken up in Restoration works : —

iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage : {

2. Damage Length : {

3. Nature of Damage : { NSL

4. Details of Restoration Works : {

i. Material being used in Restoration works : x


ii. Equipments/Tools being used in Restoration Works : 2


iii. Procedure taken up in Restoration works : 2

iv. Restored Length : >


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)