

Inspection Report for Flood Damage Work

Date.:26.12.2020...

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – L050 - Fatehabad To Chaki Suhagpur (VR28)

A. for Road

1. Damage Location/Chainage : 32 Place.

2. Damage Length : 506 M.

3. Nature of Damage : Breach at Road cross with embankment.

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Bats, Local Sand.

ii. Equipments/Tools being used in Restoration Works : Tractors, J.C.B, Rollers

iii. Procedure taken up in Restoration works : First - Bricks Bats filling in breach portion.
Then - Topping by local sand.

iv. Restored Length : 506 M.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :


i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)