

## Inspection Report for Flood Damage Work

Date.: ..... 26/12/2020

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Motipur

3. Name of Road/Bridge – Bishist singh ke ghar se to Shasna School Tak

A. for Road

1. Damage Location/Chainage : 5.2 TO 5.6 KM

2. Damage Length : 200m

3. Nature of Damage : Road cross side sub-grade eroded in the

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Ball, Local sand

ii. Equipments/Tools being used in Restoration Works : Grader, TCD, Roller

iii. Procedure taken up in Restoration works : First filling of Bricks Ball

iv. Restored Length : 200m . Broad pavement for topping layer

B. for Bridge

1. Damage Location/Chainage : X

2. Damage Length : X

3. Nature of Damage : X


4. Details of Restoration Works : X


i. Material being used in Restoration works : X


ii. Equipments/Tools being used in Restoration Works : X


iii. Procedure taken up in Restoration works : X

iv. Restored Length : X

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)