

Inspection Report for Flood Damage Work

Date.:26.12.2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – Gokula Swastha UP Kandra to Darfari Muneshwar Ray ke Ghar tak

A. for Road

1. Damage Location/Chainage : 2.25 KM

2. Damage Length : 20.00 M.

3. Nature of Damage : Breach at Road Cross with Embankment.

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Bala, Local Sand

ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller

iii. Procedure taken up in Restoration works : First - Bricks Bala filling in breach portion
Then - Topping by Local Sand.

iv. Restored Length : — 20.00 M.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :


i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :

iii. Procedure taken up in Restoration works :

iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)