

Inspection Report for Flood Damage Work

Date.: 26.12.20

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Motipur

3. Name of Road/Bridge – Middle school Mahbal TO Railway Pul dalit Basti

A. for Road

1. Damage Location/Chainage : 0.30 K.M to 0.560 K.M.

2. Damage Length : 0.253 K.M.

3. Nature of Damage : Flank and Half Portion of road.

4. Details of Restoration Works : eroded in Flood.

i. Material being used in Restoration works : Brick Bats, local sand.

ii. Equipments/Tools being used in Restoration Works : Tractor, JCB machine & Roller

iii. Procedure taken up in Restoration works : First Brick Bats filling in breach

iv. Restored Length : 260m. Portion than local sand topping.

B. for Bridge

1. Damage Location/Chainage : x

2. Damage Length : x

3. Nature of Damage : x

4. Details of Restoration Works : x

i. Material being used in Restoration works : x

ii. Equipments/Tools being used in Restoration Works : x

iii. Procedure taken up in Restoration works : x

iv. Restored Length : x

26/12/20
J.E.

26.12.20
A.E.

1/18/20
Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

26/12
Signature
(Name of Inspector)