

Inspection Report for Flood Damage Work

Date.: 26/12/2020

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Motipur

3. Name of Road/Bridge – Anjana Kot Hanuman mandir To Parsaunia Chalitra Sahani

A. for Road

1. Damage Location/Chainage : 500 to 800 m

2. Damage Length : 313 m

3. Nature of Damage : Both side of shoulder eroded in/land

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick Bat & local sand

ii. Equipments/Tools being used in Restoration Works : Puccon & JCB, Roller

iii. Procedure taken up in Restoration works : First brick bat filling & local

iv. Restored Length : sand fill.

B. for Bridge

1. Damage Location/Chainage : 0

2. Damage Length : 0

3. Nature of Damage : 0


4. Details of Restoration Works : 0


i. Material being used in Restoration works : 0


ii. Equipments/Tools being used in Restoration Works : 0


iii. Procedure taken up in Restoration works : 0

iv. Restored Length : 0


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)