

Inspection Report for Flood Damage Work

Date.: 26/12/2020

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Motipur
3. Name of Road/Bridge – Kapildev Bhagat ke Ghar Paharchak Math to Ramanand Ray ke Bathan Tak

A. for Road

1. Damage Location/Chainage : 1200 TO 1250 & 1850 TO 1950 m
2. Damage Length : 565 m
3. Nature of Damage : Y₃ Road cut with sub-grade shoulder eroded in flood.
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Brice Ball & sand Fills
 - ii. Equipments/Tools being used in Restoration Works : Grader, TCB etc.
 - iii. Procedure taken up in Restoration works : Fill Brice Ball & sand
 - iv. Restored Length :

B. for Bridge

1. Damage Location/Chainage : 0
2. Damage Length : 0
3. Nature of Damage : 0
4. Details of Restoration Works : 0
 - i. Material being used in Restoration works : 0
 - ii. Equipments/Tools being used in Restoration Works : 0
 - iii. Procedure taken up in Restoration works : 0
 - iv. Restored Length : 0

26/12/2020
J.E.

26.12.20
A.E.

26/12/20
Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west

26/12/20
Signature
(Name of Inspector)