

Inspection Report for Flood Damage Work

Date.:26.12.20.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Motipur

3. Name of Road/Bridge – Dhumnagar P.W.D. road to Bankat via Bakhri

A. for Road

1. Damage Location/Chainage : ✕

2. Damage Length : ✕

3. Nature of Damage : ✕

4. Details of Restoration Works : ✕

i. Material being used in Restoration works : ✕

ii. Equipments/Tools being used in Restoration Works : ✕

iii. Procedure taken up in Restoration works : ✕

iv. Restored Length : ✕

B. for Bridge

1. Damage Location/Chainage : 0.150 K.M.

2. Damage Length : 8 M.

3. Nature of Damage : C.D. Work Wash out in Flood.

4. Details of Restoration Works :


i. Material being used in Restoration works : Hume Pipe, Brick Bats & Local Sand


ii. Equipments/Tools being used in Restoration Works : Tractor, JCB Machine

iii. Procedure taken up in Restoration works : Hume pipe Laid in base and
brick bats filling them Local Sand
Top Layer

iv. Restored Length : 8.0 M


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)