Inspection Report for Flood Damage Work

		1	1	
Date .	261	191	2020	
Dan.	201	1.4.		

- 1. Name of PIUs Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
- 2. Name of Block Sahebganj
- 3. Name of Road/Bridge Sahpur Patti To Leodiya Chowk NH-74 Via Khamkran Mnail Tol
- A. for Road

1. Damage Location/Chainage

: 5550 TO 55757

2. Damage Length

: 257

3. Nature of Damage

:

4. Details of Restoration Works

i. Material being used in Restoration works:

Bicu au 8 some files co

- ii. Equipments/Tools being used in Restoration Works: Praclum, Jen Lee
- iii. Procedure taken up in Restoration works:
- iv. Restored Length:
- B. for Bridge

1. Damage Location/Chainage

: >

2. Damage Length

Ø

3. Nature of Damage

: }

4. Details of Restoration Works

بر:

- i. Material being used in Restoration works:
- ii. Equipments/Tools being used in Restoration Works:
- iii. Procedure taken up in Restoration works:
- iv. Restored Length:

J.E. 112 12020

26/12) 2020 A.E.

Executive Engineer, R.W.D. Works Division, Muzaffarpur west Signature (Name of Inspector)