

Inspection Report for Flood Damage Work

Date.: 26.12.20.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Motipur

3. Name of Road/Bridge – Durga Sthan Se to Sudhir Sahni Ke Chimni Tak

A. for Road

1. Damage Location/Chainage : 0.90 KM to 1.50 K.M.

2. Damage Length : 600 M.

3. Nature of Damage : $\frac{1}{3}$ rd Road Crust with sub grade shoulder

4. Details of Restoration Works : eroded in flood.

i. Material being used in Restoration works : Hume pipe & E/w only.

ii. Equipments/Tools being used in Restoration Works : Tractor, ICB etc.

iii. Procedure taken up in Restoration works : Eroded Part of road filled

iv. Restored Length : with earth and Hume pipe for crossing water.

B. for Bridge

1. Damage Location/Chainage : x

2. Damage Length : x

3. Nature of Damage : x

4. Details of Restoration Works : x


i. Material being used in Restoration works : x


ii. Equipments/Tools being used in Restoration Works : x


iii. Procedure taken up in Restoration works : x

iv. Restored Length : x


J.E.


A.E. 26.12.20


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)