

Inspection Report for Flood Damage Work

Date.:26.12.2020.....


1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Paroo
3. Name of Road/Bridge – Eakama to karpuri pmgsy road to harijan tola rupnarayanpur


A. for Road


1. Damage Location/Chainage : 10 places (From -0.00KM to 1.526KM)
2. Damage Length : 161 M.
3. Nature of Damage : Breach at Road Cross with Embankment.
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Subgrade (Earthen shoulder)
 - ii. Equipments/Tools being used in Restoration Works : -Tractor, J.C.B, Roller
 - iii. Procedure taken up in Restoration works : Earth filling in breach portion.
 - iv. Restored Length : _____ 161 M.


B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration Works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)