

## Inspection Report for Flood Damage Work

Date.: ....26.12.2020....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Paroo

3. Name of Road/Bridge – Baijalpur Dhala to Seotriya

A. for Road

1. Damage Location/Chainage : 807M, 551M, 1284M, 1406M, 2014M

2. Damage Length : 85M.

3. Nature of Damage : Breach at Road Cross with Embankment.

4. Details of Restoration Works :

i. Material being used in Restoration works : Bricks Ball, Local Sand.

ii. Equipments/Tools being used in Restoration Works : Tractor, JCB, Roller

iii. Procedure taken up in Restoration works : First - Bricks Ball filling in breach portion  
Then - Topping by Local Sand.

iv. Restored Length : 85M.

B. for Bridge

1. Damage Location/Chainage :

2. Damage Length :

3. Nature of Damage :

4. Details of Restoration Works :


i. Material being used in Restoration works :


ii. Equipments/Tools being used in Restoration Works :


iii. Procedure taken up in Restoration works :

iv. Restored Length :

  
J.E.

  
A.E.

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)