

Inspection Report for Flood Damage Work

Date.:26/12/2020.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West
2. Name of Block – Paroo
3. Name of Road/Bridge – Khutahi se Shethriya Math Hote Hue to Gyashpur


A. for Road


1. Damage Location/Chainage : 16 places (1.00 km to 5.00 km)
2. Damage Length : 331.50 M.
3. Nature of Damage : Breach at Road Crest with Embankment.
4. Details of Restoration Works :
 - i. Material being used in Restoration works : Bricks Bala, Local sand
 - ii. Equipments/Tools being used in Restoration Works : Tractor, J.C.B, Roller
 - iii. Procedure taken up in Restoration works : First - Bricks Bala filling in breach portion. Then - Topping by local sand.
 - iv. Restored Length : — 331.50 M.

B. for Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
 - i. Material being used in Restoration works :
 - ii. Equipments/Tools being used in Restoration Works :
 - iii. Procedure taken up in Restoration works :
 - iv. Restored Length :


J.E.


A.E.


Executive Engineer,
R.W.D. Works Division,
Muzaffarpur west


Signature
(Name of Inspector)