

## Inspection Report for Flood Damage Work

Date.: ...20.12.20.....

1. Name of PIUs – Executive Engineer, R.W.D., Works, Division, Muzaffarpur West

2. Name of Block – Motipur

3. Name of Road/Bridge – NH-28 Panchrukhi To Bariyarpur

A. for Road

1. Damage Location/Chainage : 1.80 to 2.0 K.M .

2. Damage Length : 109.70 M .

3. Nature of Damage : Road Crust and Side Subgrade  
eroded in Flood.

4. Details of Restoration Works :

i. Material being used in Restoration works : Brick Bats, Local Sand.

ii. Equipments/Tools being used in Restoration Works : Tractor, JCB Machine and  
Roller.

iii. Procedure taken up in Restoration works : First Filling of Brick Bats in  
Breach Portion Then Topping  
by Local Sand.

iv. Restored Length : 110 M .

B. for Bridge

1. Damage Location/Chainage : x

2. Damage Length : x

3. Nature of Damage : x


4. Details of Restoration Works : x


i. Material being used in Restoration works : x


ii. Equipments/Tools being used in Restoration Works : x

iii. Procedure taken up in Restoration works : x

iv. Restored Length : x

  
J.E.

  
A.E. 26.12.20

  
Executive Engineer,  
R.W.D. Works Division,  
Muzaffarpur west

  
Signature  
(Name of Inspector)