

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- minapuri/Log 4-707 to Karamwadi (VR 61)


(A) For Road:

- ✓
1. Damage Location/Chainage :- 1-50 km, 1-55 km
 2. Damage Length :- 0.065 km
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- gravel bags
 - (ii) Equipment's/Tools being used in Restoration works:- Trencher
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.065 km

(B) For Bridge:

- X
1. Damage Location/Chainage :-
 2. Damage Length :-
 3. Nature of Damage :-
 4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EE

RWP muzaffarpur Cent-1

GENERAL ABSTRACT

Name of Road L094-T07 to Karamwari (VR61)

District Muzaffarpur

Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 1.900 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.565
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.565
TOTAL COST OF PROJECT IN LACS =		1.565

[Signature]
11/1/21

JE
RWD

[Signature]
11/01/21

AE
RWD

[Signature]
21/01/21
EE
RWD

Technically approved for Rs 1.565 lac
(Rupees one lac fifty six thousand five hundred only)

[Signature]
13.1.21
SE

RWD work circle
muzaffarpur