

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- minapur / Bhagwanpur Khawadpur to mugher talai tal
via sah tala

(A) For Road:

1. Damage Location/Chainage :- 0-20 km, 1-00 km
2. Damage Length :- 0.055 km
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- Bricks
 - (ii) Equipment's/Tools being used in Restoration works:- Tractor
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- 0.055 km

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE


Signature

(Name of Inspection)

EG

RWD muzaffarpur East - 1

GENERAL ABSTRACT

Name of Road Bhagwanpur Khawadpur to Mushar Tola Tak Via Sah Tola

District Muzaffarpur

Block	Minapur
-------	---------

Division Muzaffarpur East-2

Length of Road (in Km)

1.536 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	3.825
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	3.825
TOTAL COST OF PROJECT IN LACS =		3.825

~~Annex 1~~
11/1/21

JE
RWD

AS 11/01/21

AE
RWD

EE
RWD

EE
RW

Technically approved for Rs 3.825 lac
(Rupees Three lac Eighty two thousand five hundred only)

SE 13.1.21

RWD work circle
muzzaffarpur