

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Kedra / Sonpur Nipin Rai Stop to Bangani Mahadevita Tala Tale  
Kodari Purniya


### (A) For Road:

1. Damage Location/Chainage :- 0.220 km
2. Damage Length :- 0.180 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- Local sand & bricks
  - (ii) Equipment's/Tools being used in Restoration works:- Tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.180 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
12.1.21  
Signature

(Name of Inspection)

EE

RWD Muzaffarpur C-1





### GENERAL ABSTRACT


Name of Road Sonpur Vipin Rai Shop to Bagmati Mahadalit Tola Tak Korai PMGSY  
District Muzaffarpur  
Block Katra  
Division Muzaffarpur East-2  
Length of Road (in Km) 1.300 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
		0.000
1	Earthwork	4.941
2	Jhama metal	3.068
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	8.009
	GRAND SUB TOTAL	8.009
TOTAL COST OF PROJECT IN LACS =		8.009


say 8.00 lac

  
11/1/21  
JE  
RWD

  
11.1.2021  
AE  
RWD

  
11/1  
EE  
RWD

Technically approved for Rs 8.00 lac  
(Rupees Eight lac only)

  
13.1.21  
SE

RWD work circle  
muzaffarpur