Inspection Report for Flood Damage Work

1550 (1985) 이 경영 전 10 10 10 10 10 10 10 10 10 10 10 10 10	
Date:-	
1 Name of PIUs:- Cryen vibraicent	
2 Name of PIUS: - Upent The Sank L 2 Name of Block/Road: - Kadoa / Darsgah Chowle to Torvun kurrors house RE o sank L Ra Jbandh D hornows tak.	ute hu
1. Damage Location/Chainage :- 0-570 lcm, 1-30 lcm	
2. Damage Length :- 0.0808 km	
3. Nature of Damage :-	
4. Details of Restoration Works:-	
(i) Material being used in Restoration works:- brick but)	
(ii) Equipment's/Tools being used in Restoration works:- Touches	
(iii) Procedure taken up in Restoration works:	
(iv) Restored Length :- 0.0808 cm	
(B) For Bridge:	
1. Damage Location/Chainage :-	
2. Damage Length :-	
3. Nature of Damage :-	
4. Details of Restoration Works:	
(i) Material being used in Restoration works:-	
(ii) Equipment's/Tools being used in Restoration works:-	
(iii) Procedure taken up in Restoration works:-	

Signature of JE/AE/EE

(iv) Restored Length

(Name of Inspection)

Signature

EE RWD M42affarpur Gall-1

GENERAL ABSTRACT

Name of Road

Dargha Chowk to Trivun Kumar House REO Sarak hote hue Rajbandh Dhanour Tak

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

Length of Road (in Km)

2.613 Km

SI. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	31.536
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.523
	GRAND SUB TOTAL	32.059
TOTAL C	OST OF PROJECT IN LACS =	32.059

Say 32.059 Jac

11

JE RWD H11.1.200

AE

RWD

EE N

RWD

Technically approved for RS 32.059 lac.

(Rubers Thirty two thousand lac five thousand mine hundred only)

SE

RWD work create

muzerflamping