

Inspection Report for Flood Damage Work

Date:

1. Name of PIUs - Gyan vibhakar
2. Name of Block/Road - minapur/ Laxi Chhosant Bazar to Chhosant
Tala Bazar (VR69)

A. For Road

1. Damage Location/Chainage : 0.020, 0.150, 0.180
2. Damage Length : 0.059 km
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works : Bricks
ii. Equipments/Tools being used in Restoration works : Tractor
iii. Procedure taken up in Restoration works :
iv. Restored Length : 0.059 km

B. For Bridge

1. Damage Location/Chainage :
2. Damage Length :
3. Nature of Damage :
4. Details of Restoration Works :
i. Material being used in Restoration works :
ii. Equipments/Tools being used in Restoration works :
iii. Procedure taken up in Restoration works :
iv. Restored Length :

Signature of JE/AE/EE


5.1.21

(Name of Inspector)

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, मुजफ्फरपुर पूर्वी-1

R.W.D.(W) Sub Division, Minapur (Muzaffarpur)					
NAME OF WORK : L021 Ghosaut Bazar Brahman Tola East (VR69)					
Sl.No.	Description of Work	Unit	Qty.	Rate per Unit	Amount
1	Supplying ,laying & spreading of Brick bats at work at site including all cost of Tax and Royalties etc.	M ³	127.71	2033.34	259678
Grand Total Rs.					259678

Rs 2.60 lakh

[Signature]
13/1/21
JE(RWD) Muz. East-2

[Signature]
13/01/21
AE(RWD) Muz. East-2

[Signature]
13/1
EE(RWD) Muz. East-2

Technically sanction for Rs 2.60 lakh
(Rupees Two lakh sixty thousand only)

[Signature]
13/1/21
अधीक्षक अभियंता
ग्रामीण कार्य विभाग
कार्य अंचल, मुजफ्फरपुर