## Inspection Report for Flood Damage Work

Date:-Kastra/ Kushbal Chowle se mughar Tolor Hote Hue Krangwardth Garale to Bamiya tolor Pari ozana Barok tike I Name of PIUs: Gyan vibhalcars 2 Name of Block/Road :-(A) For Road: 1. Damage Location/Chainage :- 0. 2001, 0.80 71, 0.88 71 1.00 11, 1-50 1000 2. Damage Length :- 0.119/cm 3. Nature of Damage 4. Details of Restoration Works: Brick bats Material being used in Restoration works:-Equipment's/Tools being used in Restoration works:-(ii) (iii) Procedure taken up in Restoration works: (iv) Restored Length :- 0.112 Km (B) For Bridge: 1. Damage Location/Chainage :-2. Damage Length 3. Nature of Damage 4. Details of Restoration Works :-Material being used in Restoration works:-(ii) Equipment's/Tools being used in Restoration works:-(iii) Procedure taken up in Restoration works:-(iv) Restored Length

Signature of JE/AE/EE

Signature

(Name of Inspection)

कार्यपालक अभियंता ग्रामीण कार्य विभाग कार्य प्रमंडल,मुजफ्फरपुर पूर्वी-1

## **GENERAL ABSTRACT**

Name of Road

Kushbal Chowk Se Mushar Tola Hote Hue Kanghura Dih Sarak to Baniya Tola Pariojana Bandh

District

Muzaffarpur

Block

Katra

Division

Muzaffarpur East-2

1.836 Km

toad (in Km) DESCRIPTION	344
Earthwork	
Jhama metal	
Sand Filling	
Sand bag	
H.P.	
GRAND SUB TOTAL	

RWD

M21 Orminal AE

Technically approved for RS 25-992 lac (Rupees Twenty five lac ninety nine thousand Two Hundred only)

अधीक्षण अस्मियंता अधीक्षण अस्मियंता अभीण कार्य विभाग कार्य अंचल, मुजपकरपुर