### Inspection Report For Flood Damage Work

	П	-	٠	-	6
- 1	u	cs	ĸ.	-	i.

1 Name of Plus: Gotalgay - 2

2 Name of Block/Road: Daikuntpus / Son Waling Mukumanton Road to
Harijan Basto Surbi 700

#### A For Road

1950 to 2020, 30000 to 3600, 590 m to 7964 1 Damage Location / Chainage:

985m \$10800, 12000 \$13000 2 Damage Length: 351 M

Heavy Rain / flood 3 Nature of Damage:

4 Details of Restroration Works:

Material being used in Restoration Works:

Brick Bats

ii Equipments / Tools being used in Restoration Works: ICB, Toactos, Tho Ci, Belokg, Skause)

iii Procedure taken up in Restoration Works:

iv Restored Length: 3 57 19

B For Bridge

NIA

- 1 Damage Location / Chainage:
- 2 Damage Length:
- 3 Nature of Damage:
- 4 Details of Restroration Works:
  - i. Material being used in Restoration Works:
  - ii Equipments / Tools being used in Restoration Works:
  - iii Procedure taken up in Restoration Works:

iv Restored Length:

(Name of Inspector)





# गामीण कार्य विभाग

Rural Works Department, Govt. of Bihar

## FLOOD DAMAGED REPAIR (F.D.R.)

STATE :- BIHAR

DISTRICT :- GOPALGANJ

BLOCK :- BAIKUNTHPUR

Sonwaliya Mukhmantri Road To Harijan Basti Surbhi Tola

ESTIMATED COST - RS.

-1515000.00 Ps 1433400 200

SUBMITTED BY :EXECUTIVE ENGINEER
RWD (W) DIVISION
COPALGANJ-2

### Report

Name of Work

:- Motorable work of Sonwaliya Mukhmantri Road To Harijan Basti Surbhi Tola

**Estimated Cost** 

:- 1515000.00 Pa 1433400 LOT

Total length of Road

- 2.195 km

:- The present estimate has been farmed under the supervision of Assistant engineer in accordance with the order of Executive Engineer, RWD, WD Gopalganj-2, letter No. - 1574 dated 18-08-2020. The part of above mentioned road has been damaged due to heavy rain/flood. And due to this damage the transporation has been obstructed. The immediate motorable work is necessary in public interest. Villagers will be benefitted by the completion of this motorable work.

In the estimate there has been a provision of repairing the damaged part of the road & making it motorable by filling brickbats. In the context of post flood scenario there is still the flow of water which prevails through the damaged part of the road.

In this estimate the rate of raw materials and labour wages has been prepared after the analysis of new rate. This estimate is as per the specifications. The estimate is devoted to technical and administrative acceptance.

J.E. J.E.

A.E.

E.E. 1919/20

# PDF Compressor Free Version led Estimate For Motorable Work in Road from SSonwaliya Mukhmantri Road harijan Basti Surbhi Tola damaged due to Heavy rain/flood for year 2020-2021

Items	No.	L (M.)	W (M.)	D (M.)	Qty.	Unit	Rate	Amount
Providing brick bats billed in ditches including all cost of labour & material with all complete job.								
CH - 195 M to 202 M	1	7.00	1.00	0,90	6.30	M3		
CH - 300 M to 360 M	2	30.00	1.50	0.70	63.00	МЗ		
CH - 590 M to 796 M	1	16:00	5.50	1.05	32,40	МЗ		
	3	30.00	0.60	0.70	37.80	HZ		
CH - 985 M to 1080 M	1	30.00	3.00	1.55	139.50	M3		
	1	18.00	2.50	1.30	58.50	М3		
	1	30.00	2.50	1.00	75.00	МЗ		
CH - 1200 M to 1300 M	1	21.00	1.50	0.90	28.35	M3		
	1	-19.00	-1.80-	1.30	-44.46	МЗ		
a a	2	30.00	1.10	1.10	72.60	М3		2015
Less for H.P.	0	1.23	1.23	0.95	0,00	МЗ	2412-11	14101682
					-617:91	M3	-2427:65	1500069:21
Providing & laying 1000 MM Dia NP3 Hume Pipe in single row -do-do- complete job.	0	2,50			584·62_ 0.00	м	27.33 · 51 4159.56	1419240.61 0.00 1419240.6
							1410168=	-1500059.21
Add 1 % Contigency							1410200	-15000.69
	KE-E						Total	1515069.90
					70		Say	<del>-1515000:00</del>

191912020

J.E.

THE STATE

STINE

15071

19.09.9090

A.E.

1919/242700.00

E.E. Surface 11 -1

Technically Approved for Ry 14.243 be (Reepes) Forteen leve Twenty four Thousand of Three 1-14 naved) only

Superintending Enginee

R W D Work, Circle-Siwan

R 11 of Levy