

## Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan vibhakar

2 Name of Block/Road :- Kadda / Bhutane se Besai


### (A) For Road:

1. Damage Location/Chainage :- 0.220 km, 0.920 km, 0.914 km, 1.51 km, 2.20 km, 2.80 km
2. Damage Length :- 0.195 km
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:- brick ball
  - (ii) Equipment's/Tools being used in Restoration works:- tractor
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :- 0.105 km

### (B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
  - (i) Material being used in Restoration works:-
  - (ii) Equipment's/Tools being used in Restoration works:-
  - (iii) Procedure taken up in Restoration works:-
  - (iv) Restored Length :-

Signature of JE/AE/EE

  
Signature

(Name of Inspection)

EG  
RWD muzaffarpur East-1



## GENERAL ABSTRACT

Name of Road      Bhutane to Berai Path

District            Muzaffarpur

Block              Katra

Division           Muzaffarpur East-2

Length of Road (in Km)

3.400 Km

		AMOUNT (LAKHS)
SI. No.	DESCRIPTION	
		0.000
1	Earthwork	9.403
2	Jhama metal	0.000
3	Sand Filling	0.000
4	Sand bag	0.000
5	H.P.	9.403
	GRAND SUB TOTAL	9.403

TOTAL COST OF PROJECT IN LACS =

say 9.40 lac

JE  
RWD

AE  
RWD

EE  
RWD

Technically approved for Rs 9.40 lac  
(Rupees nine lac forty thousand only)

SE  
12.1.21

RWD work circle  
muzaffarpur