

## Inspection Report for Flood Damage work

Date:-

- 1 Name of Pius :- Madhe pura
- 2 Name of Block :- Ghaila Y
- 3 Name of Road :- Confg of Road from Shilwanagar Road No. 03 to Lakshmi chocolate world  
Bottle Road via Ramnagar.

### A. For Road

- 1 Damage Location/Chainage :- 1.20 km, 2.70 km, 2.80 km, 3.30 km, 3.80 km, 3.85 km - 4.00 km
- 2 Damage Length :- 0.135 km
- 3 Nature of damage :- Slantes and sand crest/-
- 4 Details of Restoration Works :-
  - i Material being used in Restortion works:- Local Sand, H.P, Torice Bats
  - ii Equipments/Tools being used in Restoration works :- JCB, and tractor.
  - iii Procedure taken up in Restoration works :- Yes
  - iv Restored Length :- 0.135 km

### B. For Bridge

- 1 Damage Location/Chainage :-
- 2 Damage Length :-
- 3 Nature of damage :-
- 4 Details of Restoration Works :-
  - i Material being used in Restortion works:-
  - ii Equipments/Tools being used in Restoration works :-
  - iii Procedure taken up in Restoration works :-
  - iv Restored Length :-

Accredited  
JE (Tutor)

8/11/2020  
AE

Dee /  
30/11/2020  
EE

Signature  
Date  
20/11/2020

(Name of inspector)  
**EXECUTIVE ENGINEER**  
**Road (T) DIVISION, UDAKISHUNGANJ**

Name to work—

1

### Situation of work—

Agency by which work is executed—

Date of measurement—

No, and date of agreement.

(These four lines should be repeated at the commencement of the measurements relating to each work.)

1st and final sketch  
step 5) Some filling in  
further features as  
perspective and  
Technical specification -

$$C_{L=120cm} = 1 \times 12 \times 7.85 \times 2.69 = 253.398 \text{ cm}^3$$

~~sten No(2) pro riding and living~~

1000mm Hg, NP<sub>3</sub> H·P.

in single row do

ch: 1200 m 3 x 2-SD I 7.50 m

Standard(3) prioritizing bare  
bait & filled 127 dippers.  
including all cost

## Continuation



### Abstract of case

Sch. XLV—Form No. 134

3