

ABSTRACT OF COST

Sch. XLV—Form No. 134

3

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<p>(1/2) providing and laying of Brick bed obtained for Chimney with mechanical means - @ City rate T.M.B.P. (1) 371.63 m³ @ Rs 1856.19/m³ = Rs 689807.70</p>					
<p>(2/3) Labour for cutting 62 mm to 75 mm dia Bamboo piles to size and making shoes @ City rate T.M.B.P. (1) 47.50 m @ Rs 27.90/m = Rs 1325.25</p>					
<p>(3/5) Labour for lifting and fixing 75 mm dia bamboo runner in position at very vertical</p>					

<p>@ City rate T.M.B.P. (2) 293.30 m @ Rs 5.00/m = Rs 1466.50</p>					
<p>(4/6) Supply of Bamboo at site as per Tech Spec - @ City rate T.M.B.P. (2) 68.00 No @ Rs 158.44/each = 10773.76 = Rs 703373.22</p>					
<p>Seigniorage Fees = Rs 39504.00 Add @ 12% GST Rs 84404.79 Add @ 1% L.Cess Rs 7033.73 = Rs 834315.74 Say Rs 834316.00</p>					
<p>W. Kumar 05-01-21 J.P.</p>					
<p>ATD 05-01-21 P.T.</p>					

Continuation

[Signature]
5/11

Inspection Report for Flood Damage work

Date:- 10-01-2021

1 Name of PUS :- Sr Shalendra Kumar

2 Name of Block :- Shankapur

3 Name of Road :- Le-26-TC3 Gadda To Kajari (VR 26)

A. For Road

1 Damage Location/Chamage :- 0.320 km

2 Damage Length :- 0.155 km

3 Nature of damage :- Earthen shoulder, Road Gully

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :- 0.024 km

B. For Bridge

1 Damage Location/Chamage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

JE
N Kumar
30-12-20

AE
M
30-12-20

EE
M
30/12/20

Signature
30/12/20

(Name of Inspector)

EXECUTIVE ENGINEER
DIVISION, UDAKISHUNGANJ