

# Inspection Report for Flood Damage work

Date:-

- 1 Name of PIUS :- Madhepura  
2 Name of Block :- Mursiganj  
3 Name of Road :- NH-107 to Dinapatti puzho madhuban

## For Road

- 1 Damage Location/Chainage :- 2600 to 3160, 3500 to 3553, 4500 to 4960, 5900 to 6580, 7300 to 8354, 10,000 to 11,000  
2 Damage Length :- 1.033 KM  
3 Nature of damage :- Water logging due to heavy rainfall.  
4 Details of Restoration Works :-  
i Material being used in Restoration works:- Bricks bats, Local sand  
ii Equipments/Tools being used in Restoration works :-  
iii Procedure taken up in Restoration works :-  
iv Restored Length :- 1.033 KM

## For Bridge

- 1 Damage Location/Chainage :-  
2 Damage Length :-  
3 Nature of damage :-  
4 Details of Restoration Works :-  
i Material being used in Restoration works:-  
ii Equipments/Tools being used in Restoration works :-  
iii Procedure taken up in Restoration works :-  
iv Restored Length :-

A. Kumar  
30/12/22  
JE

AE  
30/12/22  
AE

EE  
30/12/22  
EE

Signature  
(Name of inspector)

EXECUTIVE ENGINEER  
RWD (W) DIVISION, UDAKISHUNGANJ





| Particulars             | Details of actual measurement |    |    |    | Contents of area                                    |
|-------------------------|-------------------------------|----|----|----|-----------------------------------------------------|
|                         | No.                           | L. | B. | D. |                                                     |
| <u>Abstract of coll</u> |                               |    |    |    |                                                     |
| <u>Item (1)</u>         |                               |    |    |    | providing bridge bds<br>in ditches portion.         |
|                         |                               |    |    |    | V.T.M.B.P.No-(2)                                    |
|                         |                               |    |    |    | Item (1) - 1573.57m <sup>2</sup>                    |
|                         |                               |    |    |    | or 1856.19/m <sup>3</sup> →                         |
|                         |                               |    |    |    | 2920845=                                            |
| <u>Item 2</u>           |                               |    |    |    | providing Road filling<br>filling d-ds and culverts |
|                         |                               |    |    |    | V.T.M.B.P.No-(2)                                    |
|                         |                               |    |    |    | Item (2) 251.84m <sup>2</sup>                       |
|                         |                               |    |    |    | or 554.03/m <sup>3</sup> →                          |
|                         |                               |    |    |    | 1,38,527=                                           |

|                 |  |  |  |          |
|-----------------|--|--|--|----------|
|                 |  |  |  | 3060372= |
| Add GST 12% -   |  |  |  | 367245=  |
| Add L.Cess 1% - |  |  |  | 30604=   |
| S.F -           |  |  |  | 170843=  |
|                 |  |  |  | 3629064= |

|                 |           |  |  |  |
|-----------------|-----------|--|--|--|
| <u>A. Kumar</u> | <u>A.</u> |  |  |  |
| 05/01/21        | 05.01.21  |  |  |  |
| J.E             | ME        |  |  |  |
|                 |           |  |  |  |
|                 |           |  |  |  |
|                 |           |  |  |  |
|                 |           |  |  |  |
|                 |           |  |  |  |
|                 |           |  |  |  |
|                 |           |  |  |  |

Continuation