

Sch. XLV—Form No. 134

Particulars

Details of actual measurement

stem (i)

D.

Phy. S. M. S. p. No - ⑤

Men No. ① - 217.55m3

217.55m @ R81856.19

$$= 403814 = 10$$

Rateup

$$R_x \cdot 403814 = \infty$$

Add GST @ 12%

Rx	48458-20
----	----------

Add Lc @ 1.0

Ry	4038-10
----	---------

Add SF

~~18~~ 23125 = 0

Taken

Rx 479435 = ∞

Andrade
05/11/21
JE

27/04/21

喜

Inspection Report for Flood Damage work

Date:-

1 Name of PIUS :- Madhepura

2 Name of Block :- Singhaeswar

3 Name of Road :- Consist of Road from Singhaeswar Birajli Dargi Road with 5 year maintenance.

A. For Road

1 Damage Location/Chainage :- 1.60 km, 2.20 km, 2.25 km, 3.430 km, 3.60 km.

2 Damage Length :- 0.200 km.

3 Nature of damage :- Crust

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :- yes

iv Restored Length :- 0.200 km

Bricks Bats, JCB and Grader.

B. For Bridge

1 Damage Location/Chainage :-

2 Damage Length :-

3 Nature of damage :-

4 Details of Restoration Works :-

i Material being used in Restoration works:-

ii Equipments/Tools being used in Restoration works :-

iii Procedure taken up in Restoration works :-

iv Restored Length :-

Anand kesh
JE 23/11/20

Brishu
23/11/20
AE

De
30/11
EE

Signature
(Name of inspector)

EXECUTIVE ENGINEER
RWD (M) DIVISION, UDAKISHUNCANJ