

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- Gyan Vibhakar

2 Name of Block/Road :- Suba B to Suba B

(A) For Road: ✓

1. Damage Location/Chainage :- 0.850 km, 0.976 km, 1.210 km, 1.435 km, 1.60 km, 1.75 km
2. Damage Length :- 267.8 m (0.2678 km)
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- brick bats
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :- 0.2678 km

(B) For Bridge: ✗

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

Signature

(Name of Inspection)

EE

RWD Work Division

Muzaffarpur East-I

GENERAL ABSTRACT		
Name of Road	Susta B to Susta B	
District	Muzaffarpur	
Block	Gaighat	
Division	Muzaffarpur East-2	
Length of Road (in Km)	1.740 Km	
Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	6.179
2	Sand Filling	0.000
3	Sand bag	0.000
4	Bamboo Piles	6.179
	GRAND SUB TOTAL	6.179
TOTAL COST OF PROJECT IN LACS =		

RE-DATE

Technically approved for Rs 6-199 lac
(Rupees six lac seventeen thousand nine hundred only)

अधीक्षण समित्यता
प्राप्ति काय विभाग
काय अंचल, मुजफ्फरपुर