Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :-Gyan VisLaker

2 Name of Block/Road :-

JNH - 72 Rampur Hari to madaribur learn

(A) For Road:

via Rambur village

1. Damage Location/Chainage :- ch 950, 1050, 2650 and many places 2. Damage Length

:- 171.40m

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:- Brain bak (i)

Equipment's/Tools being used in Restoration works:- Track (ii)

Procedure taken up in Restoration works: (iii)

(iv) Restored Length :- 171.40-

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works:

Material being used in Restoration works:-(i)

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Enginéer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

J NH-77 Rampur Hari to Madaripur Karn Via Rampur Village (Link No-86)

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

2.650 Km

Division		2.000 Km	
Length of	Road (in Km)	AMOUNT (LAKHS)	
SI. No.	DESCRIPTION	6.515	
1	Jhama metal	0.000	
2	Sand Filling	0.000	
3	Sand bag	0.000	
4	H.P.	6.515	
	GRAND SUB TOTAL	6.515	
TOTAL C	COST OF PROJECT IN LACS =	Su 6.51	

TOTAL COST OF PROJECT IN LACS

JΕ

RWD

· 01.51 Aclor/01/2/

Technically approved for Ps. 6.51 le (Rupers Six lae fifty one thousand only.)

Myzafforpur