## **Inspection Report for Flood Damage Work**

Date:-

Coyan Vislanar 1 Name of PIUs :-

2 Name of Block/Road :-

PWD Kar Chouli'a to Shital Patti

(A) For Road:

1. Damage Location/Chainage :- ch 270, 288, 380, 510, 600, 700 and many plus

2. Damage Length :- 87.402

3. Nature of Damage 4. Details of Restoration Works:

Material being used in Restoration works: - Brich Sas (i)

Equipment's/Tools being used in Restoration works:- Tractor (ii)

Procedure taken up in Restoration works: (iii)

87.402 Restored Length (iv)

## (B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:-(i)

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

## GENERAL ABSTRACT PWD Karchoulia to Shital Patt Name of Road Muzaffarpur District Minapur Block Muzaffarpur East-2 Division 1.100 Km Length of Road (in Km) AMOUNT (LAKHS) DESCRIPTION SI. No. 10.194 Jhama metal 1 0.000 Sand Filling 2 0.000 Sand bag 3 0.000 H.P. 4 10.194 **GRAND SUB TOTAL** 10.194 TOTAL COST OF PROJECT IN LACS =

say 10.19 lac

67.01.2021

ΑE

JE RWD

RWD

Technically approved for AS 10.19 lac (Rupeed Fen lac nimeteen thousand only)

> SE RWD WORK CITCLE musaffarper