# **Inspection Report for Flood Damage Work**

#### Date:-

1 Name of PIUs :-

Gyan Villanas

2 Name of Block/Road :-

Banua Ram bot + vas smooth to magra pub chause

### (A) For Road:

- 1. Damage Location/Chainage :- 450, 2080, 2216, 3320 and many places
- 2. Damage Length

:- 141.302

3. Nature of Damage

- 4. Details of Restoration Works: (i)
- Material being used in Restoration works:- Brich 5215
- Equipment's/Tools being used in Restoration works:- Trac liv (ii)
- Procedure taken up in Restoration works: (iii)
- (iv) Restored Length

141.3000

#### (B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- Material being used in Restoration works:-(i)
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

## **GENERAL ABSTRACT**

Name of Road

Banua Ramprit Vas Smath to Magia PWD Chowk

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

4.353 Km

| SI. No. | DESCRIPTION              | AMOUNT (LAKHS) |
|---------|--------------------------|----------------|
| 1       | Jhama metal              | 2.001          |
| 2       | Sand Filling             | 0.000          |
| 3       | Sand bag                 | 0.000          |
| 4       | H.P.                     | 0.000          |
|         | GRAND SUB TOTAL          | 2.001          |
| TOTAL C | OST OF PROJECT IN LACS = | 2.001          |

Sy lios le

JE

RWD

ΑE

RWD

EE

RWD

Technically approved for 1s. 2. vole Rupers two lae only).

> Wind Mark clarke S. E.