

Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :- *Cryan Villahar*

2 Name of Block/Road :- *NH 77 Dhamapur Narayan to maderipur Karm*

(A) For Road:

1. Damage Location/Chainage :- *490, 675, 820, 955 & many places*
2. Damage Length :- *86.60m*
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:- *Brick ball*
 - (ii) Equipment's/Tools being used in Restoration works:- *Tractor*
 - (iii) Procedure taken up in Restoration works:
 - (iv) Restored Length :- *86.60m*

(B) For Bridge:

1. Damage Location/Chainage :-
2. Damage Length :-
3. Nature of Damage :-
4. Details of Restoration Works :-
 - (i) Material being used in Restoration works:-
 - (ii) Equipment's/Tools being used in Restoration works:-
 - (iii) Procedure taken up in Restoration works:-
 - (iv) Restored Length :-

Signature of JE/AE/EE

[Signature]
15.1.21
Signature

(Name of Inspection)
R.W.D. Works Division
Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road NH 77 Dharampur Narayan to madaripur karn

District Muzaffarpur


Block Minapur

Division Muzaffarpur East-2

Length of Road (in Km) 2.962 Km

Sl. No.	DESCRIPTION	AMOUNT (LAKHS)
1	Jhama metal	1.017
2	Sand Filling	0.000
3	Sand bag	0.000
4	H.P.	0.000
	GRAND SUB TOTAL	1.017
TOTAL COST OF PROJECT IN LACS =		1.017


By 1.02 lacs


07.01.2021

JE
RWD




AE
RWD



EE
RWD

Technically approved for Rs. 1.02 lacs (Rupees one
lacs two thousand only.)


S.E.
R.W.D. work circle
Muzaffarpur