Inspection Report for Flood Damage Work

	_				
1	1	a	+,	•	
			T		

1 Name of PIUs: - Coyan Wishartar

2 Name of Block/Road :-

1. Damage Location/Chainage :- 1560 to 1615, 1675 to 1698, 1858 to 1864.50 m

(A) For Road:

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:- Brien Sals (i)

Equipment's/Tools being used in Restoration works:- Tree Cor (ii)

(iii) Procedure taken up in Restoration works:

Restored Length (iv)

:- 81.002

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

:-

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:-(i)

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer

R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

L049 T03 NH-77 Rampur Hari to Majlish Mdho Urf Chhapra (VR44)

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

2.275 Km

Length	DESCRIPTION	AMOUNT (LAKHS)
SI. No.	Jhama metal	10.410
	Sand Filling	0.000
	Sand bag	0.000
	H.P.	0.000
4	GRAND SUB TOTAL	10.410
	OST OF PROJECT IN LACS =	10.410

84 10:4/8

IE

RWD

AΕ

RWD

EE

RWD

technically approved for ps. 10.41 be Rupees ten lae fourty one thousand only.

S.E.

R.W.D. Work circle

Myzaffarbyr