Inspection Report for Flood Damage Work

\mathbf{D}	at	_		
v	aı	.e	:	-

1 Name of PIUs: - Co Jan Villakor

2 Name of Block/Road :-

mousuelpur to chapter

(A) For Road:

- :- Ch 80, 91, 94, 100, 109, 121, 134, 280 many plus 1. Damage Location/Chainage
- 2. Damage Length
- :- 42.90m
- 3. Nature of Damage
- 4. Details of Restoration Works :-
- Material being used in Restoration works:- Braich Sas (i)
- (ii) Equipment's/Tools being used in Restoration works:- Track, Truen
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length
- :- 42.902

(B) For Bridge:

- 1. Damage Location/Chainage
- 2. Damage Length
- 3. Nature of Damage
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Enginéer R.W.D. Works Division Muzaffarpur East-l

4.501	OTAL SOST OF PROJECT IN LACS =	2
4.501	COST OF DIO ISSUE	IATOT IA
0.00	GRAND SUB TOTAL	
0 000	H.P.	4
0.000	Sand bag	ω
0.000	Sand Filling	2
AMOUNT (LANNS)		1
Km	DESCRIPTION 1.200	SI. No.
	Muzaffarpur East-2 f Road (in Km)	Length
		Division
	24	District
	Name of Road Maksudpur to Chapra	Name
	GENERAL ABSTRACT	:

JE AE RWD RWD

RWD ER ATT

Jour les fifty thousand only)

Whroglerspar bino D. Mook chade