Inspection Report for Flood Damage Work

Date:-

1 Name of PIUs :-Crayan Vishanas

2 Name of Block/Road :-

Nandom Nagrenolora sahni House to Cresi gama surrondra singh House.

(A) For Road:

1. Damage Location/Chainage :- 290~ 2. Damage Length :- 9.30

3. Nature of Damage

4. Details of Restoration Works :-

(i)

Material being used in Restoration works:- Bricks

Equipment's/Tools being used in Restoration works:- Free low (ii)

(iii) Procedure taken up in Restoration works:

Restored Length (iv)

9.300

(B) For Bridge:

1. Damage Location/Chainage

2. Damage Length

3. Nature of Damage

4. Details of Restoration Works :-

Material being used in Restoration works:-

(ii) Equipment's/Tools being used in Restoration works:-

(iii) Procedure taken up in Restoration works:-

(iv) Restored Length

Signature of JE/AE/EE

(Name of Inspection) Executive Engineer R.W.D. Works Division Muzaffarpur East-1

GENERAL ABSTRACT

Name of Road

Nandan Nagendra Sahni House to Gorigama Surendra Singh House

District

Muzaffarpur

Block

Minapur

Division

Muzaffarpur East-2

Length of Road (in Km)

1.375 K	m
---------	---

Length of Moda (m. 14.17)		1,373 1(1)	
SI. No.	DESCRIPTION	AMOUNT (LAKHS)	
1	Jhama metal	7.021	
2	Sand Filling	0.000	
		0.000	
3	Sand bag	0.000	
4	H.P.	7.021	
	GRAND SUB TOTAL	7.021	
TOTAL C	COST OF PROJECT IN LACS =	7.021	

oy 7-02 lac

7/1/2021

RWD

ΑE

RWD

EE

RWD

Technically approved for RS 7.02 lac (Rupees seven lac two thousand only)

SE

RWD WORL CIVILLE

myrentferopero