## **Inspection Report for Flood Damage Work**

Date:-

1 Name of PIUs: - Cigan Viblarar

2 Name of Block/Road :-

Primary School madi Tala to sakas bur Icothi

(A) For Road:

- 1. Damage Location/Chainage :- cL 1085 to 1114.507
  - 2. Damage Length

:- 28:00 m

3. Nature of Damage

- Nature of Damage :
- 4. Details of Restoration Works:
- (i) Material being used in Restoration works:- Brien bak
- (ii) Equipment's/Tools being used in Restoration works:- Tree to
- (iii) Procedure taken up in Restoration works:
- (iv) Restored Length

:- 28.00~

## (B) For Bridge:

- 1. Damage Location/Chainage :-
- 2. Damage Length
- ٠.

:-

- 3. Nature of Damage
- 4. Details of Restoration Works :-(i) Material being used in Restoration works:-
- (ii) Equipment's/Tools being used in Restoration works:-
- (iii) Procedure taken up in Restoration works:-
- (iv) Restored Length

Signature

Signature of JE/AE/EE

(Name of Inspection).
Executive Engineer
R.W.D. Works Division
Muzaffarpur East-1

## **GENERAL ABSTRACT**

Block District Name of Road Primary School Mali Tola to Sahajpur Kothi Minapur Muzaffarpur Muzaffarpur East-2

Division	ואומבמוומו לימו במסניב	
Length of	Length of Road (in Km)	1.115 KM
SI. No.	DESCRIPTION	AMOUNT (LAKHS)
_	Jhama metal	7.434
2	Sand Filling	
		0.000
ω	Sand bag	0.000
4	H.P.	1.434
	GRAND SUB TOTAL	1.434
TOTAL C	TOTAL COST OF PROJECT IN LACS =	

Say 1.43 lanc

333.

AE RWD

RWD

3

Technically approved for RS 1:43 lac.
(Rubeel one lac soft three thousand only

AND WORK CIRCLE